



GENERAL NOTES

1. Do not scale from this drawing. Use figured dimensions only. Unless otherwise stated all drawing units are in millimetres. Levels are in meters.
2. This drawing to be read in conjunction with all other relevant consultant/specialist drawings and specifications.
3. Check levels/dimensions quoted on drawing against those on site before finalising.
4. Report any discrepancies before affected work commences.
5. For setting out dimensions, see Architect's drawings.
6. This drawing remains copyright of Blackett-Ord Conservation Ltd. Copy/distribute only with consent of the Author.

KEY

- FF1 REFERENCE TO STRUCTURAL DEFECT
- · · · — STEEL BEAMS
- ~~~~~ CRACKING

STRUCTURAL DEFECTS:

Ref.	STRUCTURAL DEFECT
FF	FIRST FLOOR
FF4	Primary beams lean down towards this elevation from the midpoint
FF5	Floor leans down towards this elevation from the midpoint
FF6	Some cracking from ceiling to window
FF8	Steps lean down – unsupported by post below



33 Chapel Street, Appleby, Cumbria CA16 6QR - Telephone: 017683 52572
Email: engineering@blackett-ordconservation.co.uk

Cockpit House, Prescott
for Purcell

First Floor Plan

Drawing No: X54/102 Rev: - Scale: 1:100 @ A3 Date: October 2021