

GENERAL NOTES

1. Do not scale from this drawing. Use figured dimensions only. Unless otherwise stated all drawing units are in millimetres. Levels are in meters.
2. This drawing to be read in conjunction with all other relevant consultant/specialist drawings and specifications.
3. Check levels/dimensions quoted on drawing against those on site before finalising.
4. Report any discrepancies before affected work commences.
5. For setting out dimensions, see Architect's drawings.
6. This drawing remains copyright of Blackett-Ord Conservation Ltd. Copy/distribute only with consent of the Author.



KEY PLAN
1:500 @ A3

KEY

B1 REFERENCE TO STRUCTURAL DEFECT

STRUCTURAL DEFECTS:

Ref.	STRUCTURAL DEFECT
B	ELEVATION B
B4	Severe mortar decay in this area, deep pack repoint and some indent repairs required.
B6	Severely decayed masonry fabric, indent repair required
B7	10mm crack below flat arch
B9	Crack increasing with height to 10mm at coping
B10	Open perpend joint in coping, ca. 10-50mm
B11	20mm diagonal crack up to coping, bricks locally displaced in this location
B12	10mm diagonal crack
B19	Vertical hairline cracks from either side of flat arch
B20	Bed joints in this section tend in different directions and bricks appear to have been displaced
B24	Vertical hairline crack
B27	Refer to Elevation A – A24. Brickwork moved outwards.
B28	Refer to Elevation A – A23. Wall rebuilt when bank use ended.
B29	Crack through voussoir requires packing and pointing

 **Blackett-Ord Conservation**
ENGINEERING

33 Chapel Street, Appleby, Cumbria CA16 6QR - Telephone: 017683 52572
Email: engineering@blackett-ordconservation.co.uk

Cockpit House, Prescot
for Purcell

Elevation B

Drawing No: X54/106 Rev: - Scale: 1:100 @ A3 Date: October 2021

