



Clock Face Prescott

Tuesday 8 October 2024

14 Issues Identified



Repoint Approx 15sqm Using Lime Mortar



Crack 1 -



Crack 1



Crack 2



Crack 2



Pillar 1



Pillar 2



Pillar 3



Pillar 4



Install New Bricks To Missing Areas



Remove Pergola



Rebuild Chimney Stack



Remove Bell Box

Remove Old Canopy To Rear Of Pub

Jonny Firth Property Manager

Daniel Thwaites