

DANIEL THWAITES PLC

ESTABLISHED 1807

To Whom it may concern,

Following the demolition of the old stables on the land adjacent to the Clock Face, Prescott, it has now given full visibility of the listed barn, adjacent to the pub. As a result, there are works required to ensure the brickwork to the external elevation is completed. Some of the works being completed on the barn have already been approved in a previous listed building application, including rebuilding of the chimney stack (complete), localised repointing and clearing of debris from rainwater goods, removal of satellite dishes and old alarm boxes.

As an employee as of Daniel Thwaites as their inhouse Chartered Building Surveyor, I attended site upon completion of the demolition of the old stables, to review the condition of the building and advise on what works are required to the building. As a result, of this the attached specification has been completed, this should be ready in conjunction with the photos of the site audit report along with the specification on the excel document.

If any further information is required please let me know.

Regards,

Jonny

Jonathan Firth Bsc. (Hons) Msc. MRICS
Chartered Building Surveyor
Daniel Thwaites Plc
Myerscough Road
Mellor Brook
Lancashire
BB2 7LB