

DYE HOUSE,
LIVERPOOL ROAD,
PRESCOT
L34 1NL

Ref: 22/00233/FUL

To whom it may concern,

I am writing this technical note in relation to a matter of confusion over the status of an existing surface watercourse culvert within Prescott Brook at a proposed development as addressed above.

It is of my understanding that a note on the drainage strategy (ref:2075-SCE-00-00-DR-C-0001) has caused some confusion over the impact to the culvert in question due to the constructions work in the near future.

Following some extensive reviews of the existing culvert and the proposals brought forward, I can confirm for the avoidance of doubt, that no remedial action will be taken on the culvert with all related structures to remain in situ.

This has been reflected in an updated drainage strategy as referenced below:

2075-SCE-00-00-DR-C-0001-P06-Drainage Strategy