



## Key

- Internal sound level exceeds BS 8233 requirement with windows open, therefore alternative means of ventilation required.
- Internal sound level may exceed Approved Document O criteria with windows open, therefore alternative means of cooling potentially required, and alternative means of ventilation as above
- Internal sound level exceeds Approved Document O criteria with windows open, therefore alternative means of cooling required, and alternative means of ventilation as above
- Red line boundary

Project: 1015946

## Figure 11.3 - Ventilation and overheating acoustic strategy

Land east of Knowsley Lane, Knowsley

Rev A: GK - 26/06/2025  
Rev B: MN - 06/08/2025

Created by: GK

HOARE LEA