

Condition 3.

All windows have added astragal bars to ensure the heritage vision of the building in accordance with details.



Condition 4:

Cycle rack and bin storage added

