

Crown West	RPA	Vigour	Amenity Value	Notes
4	7.2	G	H	A prominent tree of high amenity value. No works
0.6	1.3	G	L	Small ornamental garden tree. No works
1.6	7.2	M	M	Heavily topped. Impacted by development. To be removed
0	5.4	M	M	Heavily topped. Impacted by development. To be removed
1.5	6.6	M	M	Heavily topped. Heavily Impacted with Ivy. Impacted by development. To be removed
1	4.8	M	M	Heavily topped. Heavily impacted with Ivy. Impacted by development. To be removed
1	4.8	M	M	Heavily topped. No works
0.5	1.5	P	n/a	Very poor growth, possibly self seeded. Remove
1.2	4.8	M	L	Heavily topped. No works.
n/a	n/a	n/a	n/a	Reduced to 4.7m as a monolith. Some epicormic growth. RPA not included as not significant.
3	2.4	G	H	Neighbouring Tree of very good form.
n/a	6.6	M	M	Heavily topped group. Not impacted by proposed development. No works