



FEATURES	SURVEY ANNOTATIONS
----------	--------------------

LEVEL PREFIX ANNOTATIONS	WO WASH OUT
	UTL UNABLE TO LIFT

DISCLAIMER

ONLY MANHOLES AND SERVICES SHOWN WERE VISIBLE AT THE TIME OF SURVEY

MAN ENTRY TO SEWERS HAS NOT BEEN UNDERTAKEN, DEPTHS, PIPESIZES ETC ARE MEASURED FROM GROUND LEVEL.

DRAINAGE INFORMATION MUST BE CHECKED AND VERIFIED PRIOR TO ANY WORK COMMENCING.

BOUNDARIES SHOWN ARE PHYSICAL AND MAY NOT REPRESENT LEGALLY CONVEYANCE OWNERSHIP.

TREE SPREADS ARE SYMBOLIC ONLY AND ARE REPRESENTATIVE OF THE AVERAGE SPREAD, THE TREE CANOPY LAYER DENOTES THE TREES EXTREMITY

ALL LEVELS ARE RELATED TO O.S. DATUM (OSCR38.15)

ESTABLISHED AT SE1 USING THE LEICA SMARTNET GPS NETWORK

Reproduction in whole or in part by any means is prohibited without the prior permission of SurveyEng Limited.



--	--
