



Photo 4: Possible electric box on concrete slab located in the north eastern part of the site.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 5: Possible buried services are indicated by scars in asphalt surfacing, located in north eastern parts of site.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 6: View looking north east. Area beyond fencing is an offsite yard space associated with the adjacent Halewood International building.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 7: View of Wilson Road which bounds the eastern site boundary.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 8: View looking south at external area of building on eastern side of the site. A radiation warning pole is located in the right corner. Asbestos warnings regarding the roof are on doors.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 9: Gas inlet room with asbestos warning sites on building. Electricity substation is located in the left of photo.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 10: Dated radiation warning label on pole noted in Photo 8, likely electromagnetic. This may be associated with components of a former alarm system.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 11: Electricity substation to the right of photo has warning signs of sulphur hexafluoride. LV building to the left of photo.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 12: Access point to eastern side of building.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 13: View through windows on eastern side of the building. Shows warehouse area to be empty.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 14: View through windows on eastern side of the building. Shows area to be empty.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 15: Access points into the eastern side of the building, outside an office area.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 16: Additional access point into the eastern side of the building.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 17: Soft landscaping area, including small trees and bushes, outside the front of the eastern side of the building. A drain cover is present.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 18: Soft landscaping to the left, including small tree. A concrete slab pathway runs along eastern side of building.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 19: Flood light tower position on southern site boundary. Tall mature trees are also present.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 20: Southern end of the red brick building looking west. The doors to boiler house are to the right of the photo.

FAIRHURST

156463 – Home Bargains, Huyton

Desk Study Report

Site Photo Plan and Photos

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 21: View into boiler house through broken section of door. Access into the boiler house was not granted, therefore a review of any potential tanks could not be undertaken.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 22: Large 'firestore' tank, likely filled with water or foam and used for fire suppression. Building to the left is likely to be a pump house with diesel pumps/generators for fire suppression system.

FAIRHURST	Desk Study Report		
	Site Photo Plan and Photos		
156463 – Home Bargains, Huyton	Date: Aug 2023	Initials: PL	Appendix: F



Photo 23: Lorry loading/unloading bays to the right of the phot and the fire suppression tank located on southern side of building.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 24: Diesel tank (smells strongly of hydrocarbons) and old crate for liquid petroleum gas, located towards the southern site boundary.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 25: 2 No. Propane tanks (appear to be used for filling forklifts), located towards the southern site boundary.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 26: View looking north of the yard space area. Soft landscaping area in the left of the photo. Surface water drainage present in centre of hard surfacing.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 27: Palisade fencing along the western side and overgrown gate at the far west point of the site.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 28: Tracking runs between the warehouse and northern site boundary (view is looking west). A surface drain and damage to the warehouse cladding is visible.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 29: View is looking north. Concrete hard surfacing located in northern portion of the site. Access to adjacent sites have been fenced off.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 30: Gated access to the main portion of the site. Access to the carpark in the south eastern part of the site has been blocked off by concrete barriers.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 31: Access to the north eastern side of the site has been blocked off by concrete barriers.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 32: Car park in south eastern side of the site, looking south.

FAIRHURST

Desk Study Report

Site Photo Plan and Photos

156463 – Home Bargains, Huyton

Date:
Aug 2023

Initials:
PL

Appendix:
F



Photo 33: Car park in south eastern side of the site, looking east.

FAIRHURST	Desk Study Report		
	Site Photo Plan and Photos		
156463 – Home Bargains, Huyton	Date:	Initials:	Appendix:
	Aug 2023	PL	F

CIVIL ENGINEERING • STRUCTURAL ENGINEERING • TRANSPORTATION • ROADS & BRIDGES
PORTS & HARBOURS • GEOTECHNICAL & ENVIRONMENTAL ENGINEERING • PLANNING &
DEVELOPMENT • WATER SERVICES • HEALTH & SAFETY/CDM SERVICES

www.fairhurst.co.uk

Aberdeen	Leeds
Birmingham	London
Bristol	Manchester
Dundee	Newcastle
Edinburgh	Sevenoaks
Elgin	Taunton
Glasgow	Watford
Huddersfield	Westhill
Inverness	

FAIRHURST