

MERSEY ROD REPORT

Mersey Rod
Unit D\92
Commerce Way
Liverpool
L8 7BA



Tel: 0330 133 1101

Email: info@merseyrod.co.uk

Site Address:

Millbrooke Manor
Knowsley Lane
L34 0JN

Report

The survey was undertaken in order to determine whether the water coming from the clients property flows into the stream/brook located outside of the front of the building.

The survey was initially done from the manhole at the front of the property. However, as shown on the report the camera was obstructed by a large tap root before we are able to confirm where the drainage ran out to.

Instead, we completed a dye test in which dyed water was pumped into the surveyed manhole.

The dye did enter the stream/brook therefore confirming and allowing us to state that the drainage from Millbrooke Manor does run into the stream/brook outside.