

Project Report

KNOWSLEY LANE

KNOWSLEY

L34 0JN

	Project Information	MILLBROOKE MANOR KNOWSLEY LANE KNOWSLEY L34 0JN
Contractor: O.MORTON	Date: 15/12/23	Contractor Email:

Project Information	
Project Name	MILLBROOKE MANOR
Street	KNOWSLEY LANE
Town/Village	KNOWSLEY
Postcode	L34 0JN
Parking Restrictions	
Client Name	BRENDON
Contractor Email	
Drawing Number	
Reason	GENERAL
Contractor	O.MORTON
Export Date	15/12/23
Export Time	12:32 PM
Weather	No rain or snow (D)

Engineer:
O.MORTON

Date:
15/12/23

Contractor Email:

Section Video:
section_1

Start:
MH01

Direction:
Downstream

End:
MH01 DS

Material:
Vitrified Clay (VC)

Pipeline Size:
225


Duty:
Storm (S)

Invert:
1.7

Date:
2023-12-13

Time:
01:50

Comments:



	Section Information	KNOWSLEY LANE KNOWSLEY L34 0JN
Engineer: O.MORTON	Date: 15/12/23	Contractor Email:

Additional Information	
Invert Depth	1.7
End Depth	.
Method of Inspection	Inspection from Manhole or Inspection Chamber (C)
Pre-Cleaned	No (N)
Pipeline Length Reference	
Pipe Shape	Circular (C)

Engineer:
O.MORTON

Date:
15/12/23

Contractor Email:

Section Video:
section_1

Start:
MH01

Direction:
Downstream


End:
MH01 DS




Observation [1]:
Start manhole MH01



Observation [2]:
Water level 5% of the height



Observation [3]:
General remark CAMERA UNDER WATER



Observation [4]:
General remark ROOTS FINE

Engineer:
O.MORTON

Date:
15/12/23

Contractor Email:

Section Video:
section_1


Start:
MH01

Direction:
Downstream

End:
MH01 DS



Observation [5]:
Water level 5 % of the height



Observation [6]:
General remark ROOTS FINE



Observation [7]:
General remark TAP ROOT



Observation [8]:
Survey abandoned TAP ROOT UNABLE TO PASS

