

MERSEY ROD CCTV REPORT

Mersey Rod
Unit D\92
Commerce Way
Liverpool
L8 7BA



Tel: 0330 133 1101

Email: info@merseyrod.co.uk

Site Address:

Millbrook Manor
Knowsley Lane
L34 0JN

Date:

13/12/2023

Report

Survey was conducted from manhole at front of the property. The manhole itself was in good condition and around 15% surcharged.

The upstream line leads directly to Millbrooke Manor. All flush tests from this direction indicate that the drainage is in good condition and flowing well.

The downstream line was then surveyed. The camera was immediately submerged in water causing a loss of vision. We continued to push on until the water level dropped and here there were roots infiltrating the drain.

We then continued and came to a large root which we were unable to pass as seen on page 6 observation 7. However, we then located the camera head and it showed that the line appeared to be running past the brook and into the road.

Any further questions or queries please don't hesitate to get in touch.

Many Thanks,

Oliver Morton

Drainage Engineer