

Appendix IV: Photographs





Plate 1 Dust Sweeping



Plate 2 Dust Suppression






Plate 3 Fencing of Excavations and the Site Boundary



Plate 4 Risk to Infrastructure





Plate 5 Vegetation Removal




Plate 6 Topsoil Stripping Across David Wilson Phase 1





Plate 7 Removal of Topsoil from David Wilson Phase 1



Plate 8 Removal of Obstructions and Relic Services





Plate 9 Segregation of Materials and Waste



Plate 10 Imported 6F2 (6F2-102, Cheshire Soils)





Plate 11 Imported 6F2 (6F2-105, Kirkby Skips)



Plate 12 Imported 6F2 (6F2-106, SED)





Plate 13 Removal of Heave Impacted Clay Soils



Plate 14 Removal of Heave Impacted Clay Soils





Plate 15 **Removal of Heave Impacted Clay Soils**



Plate 16 **Removal of Heave Impacted Clay Soils**





Plate 17 Removal of Heave Impacted Clay Soils



Plate 18 Upfill with Site-Won Granular / Non-Heave Impacted Cohesive Materials






Plate 19 Upfill with Site-Won Granular / Non-Heave Impacted Cohesive Materials



Plate 20 Upfill with Site-Won Granular / Non-Heave Impacted Cohesive Materials





Plate 21 **Upfill with Site-Won Granular / Non-Heave Impacted Cohesive Materials**



Plate 22 **Upfill with Site-Won Granular / Non-Heave Impacted Cohesive Materials**

