





File Name: G22558 - 8100 Main Location Hollywood 8rvA.c

[illegible]

NOTES:
All levels relate to O.S. (Newlyn) Datum. Established using network

Services shown as "Trans Statutory Authority Plans" line styles are taken from Statutory Records plans supplied by the relevant regional authority. These services were not located and are shown for information purposes only.



DISCLAIMER:

As GEO UK LTD we are skilled and experienced staff, modern up to date techniques and top of the range electromagnetic and radar technology to locate and trace sub-surface utilities. However the performance of the equipment employed in non-invasive surveys can be adversely affected by factors outside the control of GEO UK LTD. Therefore GEO UK LTD cannot guarantee that all utilities present on site have been located. It is the responsibility of the Client to consult regional authority records and undertake trial digs where appropriate.

Where similar services run in close proximity it may be impossible to separately trace individual services as the trace signal can experience interference. In such cases, services will be shown as a single, annotated line. The displayed depth will refer to the shallowest detected utility.


Successful tracing of non-conductive materials may be limited. Drainage gulleys are dye tested where possible to prove connectivity but it is not always possible to introduce the sonde due to narrow pipe sizes and/or

Depth information of underground services/features are generally accurate to within +/- 10% [i.e. a pipe at 2m deep may be accurate to +/-200mm] but this cannot be guaranteed. Depths shown usually refer to the top of the service. Gravity sewer and drain depths are usually to invert (base of drainage channel) unless otherwise stated.


Some above ground features may have been obscured at time of survey. It is not always possible to operate the Ground Penetrating Radar in areas including, but not limited to, dense vegetation, rubble, debris and/or rough/uneven ground.

Existing record information that was made available to GEO UK LTD by the

Excavation in the vicinity of services shown should be carried out with due diligence [ref. HSG47].



A	MAR22	Added Survey
REV	DATE	DESCRIPTION



Client
Redrow

Project Title
Rising Main Location
Holewood

Surveyed A.L.		Drawn G.B.		Checked J.S.		
Scale 1:250	Date Jan 21	Drawing Ref. S21-HW-P		No. 01	Size A0	Rev A

DISCLAIMER:

At GEO UK LTD we use skilled and experienced staff, modern up to date techniques and top of the range electromagnetic and radar technology to locate and trace subsurface utilities. However the performance of the equipment employed in non-invasive surveys can be adversely affected by factors outside the control of GEO UK LTD. Therefore GEO UK LTD cannot guarantee that all utilities present on site have been located. It is the responsibility of the Client to consult regional authority records and undertake trial digs where appropriate.

Where similar services run in close proximity it may be impossible to separately trace individual services as the trace signal can experience interference. In such cases, services will be shown as a single, unannotated line. The displayed depth will refer to the shallowest detected utility.

Successful tracing of non-conductive materials may be limited. Drainage gullies are dye tested where possible to prove connectivity but it is not always possible to introduce the dye due to narrow pipe size and/or accumulated silt.

Depth information of underground services/features are generally accurate to within +/- 10% (i.e. a pipe at 2m depth may be accurate to +/- 200mm) but this cannot be guaranteed. Depths shown usually refer to the top of the service. Clearly shown and clear depths are given in green boxes of drainage channels) unless otherwise stated.

Some above ground features may have been obscured at time of survey. It is not always possible to separate the Ground Penetrating Radar in areas including, but not limited to, dense vegetation, rubble, debris and/or rough/uneven ground.

Existing record information that was made available to GEO UK LTD by the Client or by the statutory utility provider should be regarded only as an indication and cannot be guaranteed.

Excavation in the vicinity of services shown should be carried out with due diligence (Ref. HSG47).

