



Photograph No. 1 – Detail of unbonded corner long elevation and end wall.



Photograph No. 2 – Unbonded corner detail side elevation and party wall.



Photograph No. 3 – Detail of wall plate



Photograph No. 4 – Close up of purlin with evidence of woodworm and beetle attack.



Photograph No. 5 – Detail of timber truss.



Photograph No. 6 – View of gable end with high level opening.



Photograph No. 7 – View of party wall with high level opening.



Photograph No. 8 – Typical view of external elevation show condition of brickwork and pointing.



Photograph No. 9 – Detail at corner side/end gable at wall plate level.



Photograph No. 10 – Detail of longitudinal distortion in purlin.

Thehovels, Tarbock Hall, Ox Lane,Prescot – E20592