



QUADRANT
APPROVED INSPECTORS
BUILDING CONTROL

Site Inspection Report

Project reference	22-78730
Your reference	
Inspection number	1
Inspection date	15/06/2022
Project description	Garage conversion
Site	27 Ambleside Drive, Kirkby, Liverpool, Merseyside, L33 2EE
Inspector	Kevin Fitzpatrick
Client	Ms Janine Jackson
Site contact	
Inspection carried out with	Home owner

Required actions

Actions	Insp. No.
Current inspection	
No required actions	
From previous inspections	
No required actions	

Inspection notes