



FRONT ELEVATION



REAR ELEVATION



SIDE ELEVATION 01



SIDE ELEVATION 02

LEGEND




HAZARDS

H1 - Potential asbestos in roof of out building
Identify if the part of the building likely to be disturbed contains asbestos and, if so, its type and condition.
If you are an employer, you should check relevant information, such as that contained in construction plans or provided by dutyholders in asbestos surveys or registers.
If no records are available, or you are unsure about their accuracy, you may need to arrange a survey and analysis of representative samples to determine the presence, type and condition of asbestos.
Refer to HSE guidance for further information: www.hse.gov.uk/publications/guidance/a9.pdf

ELEVATION MATERIAL KEY

1. Brickwork
2. Timber Frame Sash Window
3. Roof Tile
4. Feature Stone Head and Cill

KEY PLAN



0m 1m 2m 5m 10m

Revision	Date	Description
----------	------	-------------

REVISION NOTES

Additional Notes
Drawing to be scaled for Planning purposes ONLY
Copyright of this drawing belongs solely to Acacia Architects
All dimensions on this drawing are shown in millimeters unless stated otherwise.
All dimensions and levels on this drawing are to be checked by the contractor and any discrepancies must be reported back to the Architect prior to the commencement of works.
Please refer to M+E drawings for all Mechanical and Electrical information.
Please refer to SE Drawings for all Structural, Connection and Underground Details.

ACACIA Architects

acaciaarchitects acacia.architects@outlook.com

ISSUED FOR:

PLANNING

Job: Grove Farm
Client: Mr G. Pary
Drawing Title: Existing Elevations
Date: 14/09/2025
Drawing no: 054 - 03 revision:
Scale: 1: 100 @ A1